

Fig. 1
Prior Art





FIG 2



CCL Dispensing Systems

Threader and Lid
In "As Shipped Condition"

6/16/03




Fig. 3





FIG 4




ECL DISPENSING
CONFIDENTIAL
6/16/03

Threader Being
Pulled from Cannister

Arms Spreading

FIG. 5



CCL DISPENSING
CONFIDENTIAL
6/16/03

Threader Partially
Removed from Lid,
Threader engaged
with Wipe

FIG. 6




FIG. 7




Fig. 8